APPLICANT: MOTOROLA, INC FCC ID: IHDT6ZC1

TRANSCEIVER ADJUSTMENTS/TUNE-UP PROCEDURE

There are no user accessible adjustments or tuning in this Fixed PCS Unit transceiver. All necessary adjustments and tuning are performed during manufacture of the product. Any Adjustments or tuning after service or repair are done as part of that process as special equipment is required to perform such adjustments.