

Polar 5B Internal pictures



CONFIDENTIAL

19 January 2022



Figure 1. Whole device from both sides.




Figure 2. The display module separated.



CONFIDENTIAL

19 January 2022




Figure 3. The connectors screws have been removed.



Figure 4. The main PWM has been removed.



CONFIDENTIAL

19 January 2022




Figure 5. The main PWB from component side.




Figure 6. The main PWB from vibra motor side.




Figure 7. Component details 1.



CONFIDENTIAL

19 January 2022




Figure 8. Component details 2.




Figure 9. Battery removed and OHR PWB visible.



CONFIDENTIAL

19 January 2022




Figure 10. OHR PWB removed.




Figure 11. OHR PWB from component side.



CONFIDENTIAL

19 January 2022




Figure 12. OHR PWB component details 1.




Figure 10. OHR PWB component details 2.




Figure 114. OHR PWB from other side.

