

American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

September 2, 2001

RE: National Datacom Corporation  
FCC ID: IOU0640S01

All of these comments are procedural and should be fairly quick to resolve.

- 1.) Please submit new Form 731 showing the RF output rated in terms of conducted power.
- 2.) The External Photos folder shows a single 0 byte file. Please resubmit.
- 3.) All cover letters are 0 byte files. Please resubmit
- 4.) The following Internal photos are 0 byte files: IntPho-1; IntPho-2. Please resubmit.



William H. Graff  
Examining Engineer  
President and Director of Engineering  
<mailto:whgraff@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.