

Table of Modification

1. Charging method:

Modified: charging-bay on the Rx providing the Tx charging via the metallic charging-strip on each side. (AC-DC adapter is plugged with the Rx DC jack)

Original: the AC-DC adapter is plugged directly to the DC jack on Tx.

2. Component:

Modified: a. by adding 2 metallic charging-strips on the on both side.
b. removing the DC jack on the Tx.

Original: (Undo the modified part in the section)

3. Soldering:

Modified: connecting both positive and negative polarity power to the bottom-end charging-strips.

Original: connecting both positive and negative polarity power to the DC input jack.

4. Mechanism:

Modified: equipped no DC jack but with the charging metallic strip at the bottom.

Original: (Undo the modified part in this section)