



Internal photographs of GMR20, GMR40.


Covers removed





Transmitter solder side



Transmitter component side



300 volt supply



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR20, GMR40
Test #: 040428
Test to: FCC Parts 2 and 80

FCCID#: IPH-0058501

Page 3 of 7

IPH00610 IntPhot.doc 9/8/2004

Detector



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214



Garmin International, Inc.
MODEL: GMR20, GMR40
Test #: 040428
Test to: FCC Parts 2 and 80

FCCID#: IPH-0058501



Page 4 of 7

IPH00610 IntPhot.doc 9/8/2004



Processor



Down Converter



Receiver



ROGERS LABS, INC.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214

Garmin International, Inc.
MODEL: GMR20, GMR40
Test #: 040428
Test to: FCC Parts 2 and 80

FCCID#: IPH-0058501

Page 7 of 7

IPH00610 IntPhot.doc 9/8/2004