




APPENDIX B. Internal Photographs of EUT





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B2 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B


Rev.01





590924





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B5 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B7 OF B66


REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01







SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B10 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01






590924





BT



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B13 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



BT



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B14 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



BT



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B15 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01




GSM






GSM






GSM





GSM



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B19 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





GSM







GSM









SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B24 OF B66


REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B26 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B27 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



WLAN



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B28 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



WLAN



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B29 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



WLAN



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B30 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01




WLAN





WLAN



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B32 OF B66

REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



590924



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B33 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B34 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B35 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B36 OF B66


REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B38 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B39 OF B66


REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B41 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B42 OF B66


REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B44 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B45 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B46 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B47 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B48 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B49 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B51 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B53 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B54 OF B66


REPORT ISSUED DATE : Nov. 29, 2005


FCC ID : JYV-V33IG-W-B


IC ID : 4947A-V33IG-W-B

Rev.01









SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B58 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B


Rev.01







590924



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

PAGE NUMBER : B61 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B62 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255


PAGE NUMBER : B63 OF B66

REPORT ISSUED DATE : Nov. 29, 2005

FCC ID : JYV-V33IG-W-B

IC ID : 4947A-V33IG-W-B

Rev.01





590924

