

Dec. 27th, 2012

Letter of Attestation

Model: TS-990S Scanning receiver (FCC ID: K44412000)

This letter attests to the fact that KENWOOD scanning receiver model TS-990S meets the requirements of the FCC Rules, 15.121(a). Compliance is achieved through the following method(s):

- (1). The Microprocessor employed has internal flash memory, however the programming information cannot be read out from the Microprocessor, therefore it has same means of protection as a masked Microprocessor .
- (2). The Microprocessor is not to accept programming, selection, scanning or direct entry of Cellular band frequencies.
- (3). The tuning control and filtering circuitry of the receiver is controlled by a microprocessor firmware, which is unalterable by the user (and it is also unalterable by the manufacturer's own support and distribution staff, and their resellers).
- (4). It is subminiature SMD assembly and inaccessible multi-layer PCB construction, any attempts to modify the equipment to receive transmissions from the Cellular Radiotelephone Service likely will render the receiver inoperable.



Tamaki Shimamura
Communication Equipment Division
JVC KENWOOD Corporation