



Washington Laboratories, Ltd.
7560 LINDBERGH DRIVE
GAITHERSBURG, MD 20879
(301) 417 - 0220 FAX # (301) 417 - 9069

October 17, 2006

Mr. Timothy Johnson
American Telecommunications Certification Body Inc.
6731 Whittier Ave
McLean, VA 22101

RE: Comments of October 17, 2006
APPLICATION: KB5-CB500LR Matric Limited

Dear Mr. Johnson:

Below are the comments that you have provided regarding the application for certification referenced above. Our responses to those comments are in ***bold italic***. Many responses refer you to additional exhibit(s) which has been uploaded to the application folder at the ATCB website.

Thank you for your attention. Please feel free to contact us for any additional information that you may require.

Regards,

Gregory M. Snyder
Chief EMC Engineer, Wireless/Telco Services Manager

Brian J. Dettling
Documentation Specialist

WLL Project: 9233

1) The response mentions the Yagi was retested. However it does not appear a new test report has been provided. It would be expected some results, especially bandedge, may change. Please explain.

R. The response is referring to the original testing. The "retesting" of the Yagi antenna in the correct position was performed at the time the incorrect antenna positioning was discovered. No new data was obtained for the response.