



17595 Mt. Herrmann, Fountain Valley
California 92708, United States
D-Link Corporation

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Attention: Application Examiner / Review Engineer
Subject: Request to change identification per section 2.933 of FCC rules

Date: 2019-04-19
Reference: FCC ID: KA2SPW118A1

To The Commission:

This Change of Identification request applies for a new FCC ID: KA2SPW118A1 as established in 47CFR 2.933(b) for a currently approved device. This application by D-Link Corporation will establish a new FCC ID under (KA2) grantee code for purpose of marketing. The original grant to FCC ID: 2AB2Q-7APLWA1 (original ID) will remain in effect.

An authorization letter by LEEDARSON LIGHTING CO., LTD. is attached.
Per 2.933(b)

1. The original identification is FCC ID: 2AB2Q-7APLWA1
2. The original grantee date is 04/25/2019
(The original certificate shall be signed and approved by the certification authority)
3. The equipment is electrically identical. Only the FCC ID number and model no. are different.
4. The original test results are applicable and representative of this changed device .
5. Exterior photographs are included in this application.

This following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format location

Sincerely yours,

A handwritten signature in black ink, appearing to read 'Howard Kao', written over a horizontal line.

Howard Kao/ Director
D-Link Corporation
Tel: 886-2-6600-0123#5692
E-mail: Howard.Kao@dlinkcorp.com