



1274 Anvilwood Ave., Sunnyvale, CA 94089 USA
Tel.: 408.732.9162 Fax.: 408.732.9164 <http://www.baclcorp.com>

2009-07-30

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

RE: Request to supersede test report for FCC ID: KNY821191151819

To Whom It May Concern:

Regarding FCC ID: KNY821191151819; we are requesting to supersede the original test report due to an error was made in the measurement of Occupied Bandwidth. On page 15 and 16 of the original report that was uploaded on 03/21/2008, the Resolution Bandwidth (RBW) used was 3.0 KHz, but the correct Resolution Bandwidth (RBW) in our verification measurement recently should be 300 Hz. Therefore, the Occupied Bandwidth should be 9.65 KHz instead of incorrectly reported 12.5 KHz and the Emission Designator will also have to be changed on the FCC Grant to 9K65F1D instead of 12K5F1D. We would like to upload the corrected test report per the clients request so that we may correct this error.

Thank you very much.

Sincerely,

**Jessica Jiang, Technical Writer
Document Control Department**
Bay Area Compliance Laboratories Corp.
1274 Anvilwood Avenue
Sunnyvale, CA 94089, USA
Tel: (408)-732-9162 (**Ext.3040**)
Email: document.control@baclcorp.com