

Re: Class II for Lear Corporation
RFAX FOB Redesign
FCC ID: KOBGT04A
IC: 3521A-T04A

RFAX Circuit Changes

Lear Corporation's original RFAX FOB has two components, its SAWR (Surface Acoustic Wave Resonator) and its RF Transistor that are EOL (end of life), meaning Lear Corporation can no longer purchase these components to build the FOBs as originally certified.

For the updated PCB employed in this application, EOL components have been replaced with the closest matching components available, and minor re-tuning of the oscillator has been performed to align the new PCB's performance to that of the original product.

The set of FOBs employing this PCB are no longer sold with vehicles by General Motors Company, but are still made available through vehicle service distributors for past vehicle models. The following model/PNs will continue to be sold as service parts using the new PCB, and fall under this Class II change / Re-assesment:

**22733524, 15114374, 15114375, 15114376,
15252034, 15777636, 15788021, 15788020**

The following model/PNs are no longer produced by Lear Corporation and are not subject to this Class II change / Re-assesment:

**10305091, 10305092, 15100811, 15100812,
15100813, 15219712, 22733523**