

Helen Zhao

Subject: FW: Chungear Industrial Co., Ltd., FCC ID: KUJ9302, Assessment NO.: AN04T4199, Notice#1



6. Test Report
(KUJ9302)-Revis...

From: Audix
Sent: Monday, September 20, 2004 1:59 AM
To: Helen Zhao
Subject: Re: Chungear Industrial Co., Ltd., FCC ID: KUJ9302, Assessment NO.: AN04T4199, Notice#1

Dear Helen,
Reply to Question #1:
The bandwidth 0.0513 MHz recorded in the report is erroneous, the correct bandwidth is 56.3 KHz.
The plot is correct. Our engineer mistook the record of bandwidth.
I have revised our report. (attached please fine file
I am sorry for our error.

Thank you,

Best Regards,
Monica Chang

>
> -----Original Message-----
> From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
> Sent: Friday, September 17, 2004 5:13 PM
> To: Helen Zhao
> Subject: Chungear Industrial Co., Ltd., FCC ID: KUJ9302, Assessment NO.:
> AN04T4199, Notice#1
>
>
> Question #1: The test report said the bandwidth is 0.0513 MHz, however the
> test plot shows 56.3 KHz, please explain.
>
> Best regards,
> Helen Zhao
>
> The items indicated above must be submitted before processing can continue
> on the above referenced application. Failure to provide the requested
> information within 30 days of the original e-mail date may result in
> application dismissal and forfeiture of the filing fee. Also, please note
> that partial responses increase processing time and should not be
submitted.
> Any questions about the content of this correspondence should be directed
to
> the e-mail address listed below the name of the sender.
>