

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCM71UW		Page 1(5)
Author Data Daoud Attayi	Dates of Test July 06-Aug 06, 2009	Report No RTS-1689-0908-38	FCC ID L6ARCM70UW

Annex E: Test Setup Photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCM71UW		Page 2(5)
Author Data Daoud Attayi	Dates of Test July 06-Aug 06, 2009	Report No RTS-1689-0908-38	FCC ID L6ARCM70UW



Figure 1 - BlackBerry® Smartphone

Author Data
Daoud Attayi

Dates of Test
July 06-Aug 06, 2009

Report No
RTS-1689-0908-38

FCC ID
L6ARCM70UW




Figure E2: Probe calibration and reference signal measurement setup





Figure E3: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RCM71UW			Page 5(5)
Author Data Daoud Attayi	Dates of Test July 06-Aug 06, 2009	Report No RTS-1689-0908-38	FCC ID L6ARCM70UW	




Figure E4: Audio Band Magnetic (ABM) T-Coil measurement setup