

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW</b>	Page <b>1(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Mar. 09-10, 2011</b>	Report No <b>RTS-3640-1103-10</b>



### **Annex E: Test set up photos**

	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW</b>	Page <b>2(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Mar. 09-10, 2011</b>	Report No <b>RTS-3640-1103-10</b>




**Figure E1. BlackBerry Smartphone**

<b>RIM Testing Services™</b>	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW</b>	Page <b>3(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Mar. 09-10, 2011</b>	Report No <b>RTS-3640-1103-10</b>



**Figure E2: Ambient noise and system validation measurement setup**

<b>RIM Testing Services™</b>	Document <b>Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDM71UW</b>	Page <b>4(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Mar. 09-10, 2011</b>	Report No <b>RTS-3640-1103-10</b>   FCC ID <b>L6ARDM70UW</b>



**Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup**