

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 1(4)	
Author Data Daoud Attayi	Dates of Test May 12-27, June 20, 2011	Report No RTS-2579-1107-19B	FCC ID L6ARDD70UW L6ARDX70UW

Annex E: Test set up photos

 RIM Testing Services™	Document	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW/RDX71UW	Page
	Author Data Daoud Attayi	Dates of Test May 12-27, June 20, 2011	Report No RTS-2579-1107-19B
			FCC ID L6ARDD70UW L6ARDX70UW

Audio Output (0, 0)

Telecoil (-5mm, 13mm)



Figure E1. BlackBerry Smartphone

RIM Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 3(4)
Author Data Daoud Attayi	Dates of Test May 12-27, June 20, 2011	Report No RTS-2579-1107-19B





Figure E2: Ambient noise and system validation measurement setup

RIM Testing Services™	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RDD71UW/RDX71UW	Page 4(4)
Author Data Daoud Attayi	Dates of Test May 12-27, June 20, 2011	Report No RTS-2579-1107-19B




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup