

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFQ111LW			Page 1(4)
Author Data Daoud Attayi	Dates of Test April 18-24, 2013	Report No RTS-6026-1304-48	FCC ID L6ARFQ110LW	

Annex E: Test set up photos


	Document			Page
	Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFQ111LW			2(4)
Author Data Daoud Attayi	Dates of Test April 18-24, 2013	Report No RTS-6026-1304-48	FCC ID L6ARFQ110LW	

Telecoil (-4, -8 mm)

Audio Output (0, 0)



Figure E1. BlackBerry Smartphone



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFQ111LW		Page 3(4)
Author Data Daoud Attayi	Dates of Test April 18-24, 2013	Report No RTS-6026-1304-48	FCC ID L6ARFQ110LW





Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RFQ111LW			Page 4(4)
Author Data Daoud Attayi	Dates of Test April 18-24, 2013	Report No RTS-6026-1304-48	FCC ID L6ARFQ110LW	





Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup