

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2)		Page 1(4)
Author Data Daoud Attayi	Dates of Test Feb. 02-17, 2015	Report No RTS-6063-1503-10	FCC ID L6ARHC160LW

Annex E: Test set up photos

	Document		Page
	Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2)		2(4)
Author Data Daoud Attayi	Dates of Test Feb. 02-17, 2015	Report No RTS-6063-1503-10	FCC ID L6ARHC160LW



Figure E1. BlackBerry Smartphone

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2)		Page 3(4)
Author Data Daoud Attayi	Dates of Test Feb. 02-17, 2015	Report No RTS-6063-1503-10	FCC ID L6ARHC160LW





Figure E2: Ambient noise and system validation measurement setup

	Document Appendix E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RHC161LW (STR100-2)			Page 4(4)
Author Data Daoud Attayi	Dates of Test Feb. 02-17, 2015	Report No RTS-6063-1503-10	FCC ID L6ARHC160LW	




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup