



# Intertek Testing Services

ETL SEMKO

Report No.: 99009511

Tested By: Hong, Report No.: 99009511


Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |       |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement: X QP

| Transducer No. | Start | Stop | Name  |
|----------------|-------|------|-------|
| 3              | 9k    | 30M  | EI078 |

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB



Ctrl. No.: N/A



# Intertek Testing Services

ETL SEMKO

Report No.: 99009511

Tested By: Hong, Report No.: 99009511

Scan Settings (1 Range)

| ----- Frequencies ----- |      |      | ----- Receiver Settings ----- |          |        |       |        |       |
|-------------------------|------|------|-------------------------------|----------|--------|-------|--------|-------|
| Start                   | Stop | Step | IF BW                         | Detector | M-Time | Atten | Preamp | OpRge |
| 450k                    | 30M  | 5k   | 10k                           | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement Results:

no Results

Ctrl. No.: N/A