

TCC Oulu
Kare Oksanen

Oct 4, 2002

1 The FCC requires separate test setup files and report files. Please separate the test setup photos and provide them as a separate file.

All photos have been captured into a separate document, which has been uploaded into your server.

2 The voice bandwidth plot on page 22 of the report does not seem to have the typically expected characteristics of a 2500Hz modulated signal. Please explain.

It looks like 2500Hz sine wave was overdriven with too high signal level. Below is the plot with correctly leveled 2500Hz sine wave.

