









COMPANY		ACTIONTEC ELECTRONICS			
BOARD		802P125			
LAYER		BOTTOM SIDE			
NO	04142A	REV: 2A	DATE: 8/13/01		
-MASTER ARTWORK-					




COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		GND PLANE	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			




COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		PASTE MASK TOP	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			


COMPANY	ACTIONTEC ELECTRONICS		
BOARD	802P125		
LAYER	SILKSCREEN TOP		
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			




COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		SOLDERMASK BOTTOM	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			



COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		SOLDERMASK TOP	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			



COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		TOP SIDE	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			



COMPANY		ACTIONTEC ELECTRONICS	
BOARD		802P125	
LAYER		VCC PLANE	
NO	04142A	REV: 2A	DATE: 8/13/01
-MASTER ARTWORK-			