

Description of Changes

on
FZV Transmitter, FCC ID LX8FZVS
of
Bayerische Motoren Werke AG

The following modifications have been made:

For design reasons a metal plate was affixed to the cabinet of the transmitter. Although the plate does not have electrical contact to the TX circuit, there is a potential effect on TX power and spurious emissions due to close proximity to the TX antenna structure on the PCB.

