

June 17, 2008

RE: ATCB006340 – Class II Permissive Change / IC Existing Family

FCC ID: M3N5WY7977 & IC: 267F-5WY7977 for Continental Automotive/Siemens

The following is in response to the comments made on the above referenced application.

1. Please provide an FCC ID label exhibit with the correct FCC ID number shown on it. There is no grant for FCC ID number M3N-5WY7977. Please see the second attachment to the email containing this request for a copy of the existing FCC grant of Certification for this device. If you do not believe me, try to find FCC ID: M3N-5WY7977 on the FCC Database (the dash does not exist).

Our apologies. We thought that the typographical error was originally our fault, and did not notice that the label provided did not match the original grant application. The ID label exhibit has been updated by the manufacturer to show the proper ID number.

Please use the originally uploaded documents that show the correct FCC ID number.

2. Please provide an FCC application form with the correct company address on it (2400 Executive Hills Drive, Auburn Hills, MI 48326) and the correct FCC ID number on it (M3N5WY7977).

The application form has been updated.