



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 26, 2004

RE: Z Com Inc.

FCC ID: M4Y-0835C

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The performance check given in plot #7 does not appear to match the data in the report (i.e. – page 17). Please explain and/or correct.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.