



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

January 7, 2003

RE: Polycom, Inc.

FCC ID: M72BTMOD01

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a block diagram that shows the frequencies of all the oscillators in the TX portion of the device (CFR 2.1033(a)(5)).
- 2) Please provide a photograph or drawing show the placement of the label on the device.
- 3) Please adjust the modular approval letter to reference the correct antenna connector.
- 4) The users manual should include an explanation to the OEM integrator that the end user should NOT be provided any instructions on how to remove or install the device.

A handwritten signature in black ink, appearing to read "Timothy R. Johnson".

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.