



Report No.: 0114006
Receiving

Tested By: Hong, Report No.: 0114006


Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services
ETL SEMKO

Report No.: 0114006
Receiving

Tested By:Hong, Report No.:0114006

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

7.19500	7.4	48.0
---------	-----	------

* limit exceeded