

Correspondence Summary

January 14, 2008

SUBJECT: *MITAC TECHNOLOGY CORP. - FCC ID: MAU300*

TCB question:

Internal Photos – page 4/16pdf RF exposure: It shows a WiFi antenna located near the left hinge of the display in the keyboard section of the laptop. If this is the case for this model of laptop, the antenna is located at <20cm and would require SAR evaluation. Please explain.

Applicant's Answer:

The antenna is only for Rx.

TIMCO ENGINEERING INC.
849 NW State Road 45
Newberry, Florida 32669
<http://www.timcoengr.com>
888.472.2424 F 352.472.2030
tei@timcoengr.com