

FEDERAL COMMUNICATIONS COMMISSION
Laboratory Division
7435 Oakland Mills Road
Columbia, MD 21046

June 09, 2004

Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037

Attention: Mike Kuo

Re: Application Received: 3/24/2004
Equipment Class: JBP-Part 15 Class B Computing Device Peripheral
Applicant Name: ImageQuest Co Ltd
FCC ID: PJIET1947L
TCB Name: Compliance Certification Services
731 Confirmation Number: TC652535

Gentlemen:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

Request by TCB in 26 May 2004 in correspondence 12096.

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before resubmitting. Do not resubmit the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications.

You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Martin Perrine
Electronics Engineer

FEDERAL COMMUNICATIONS COMMISSION
Laboratory Division
7435 Oakland Mills Road
Columbia, MD 21046

June 09, 2004

ImageQuest Co Ltd
San 136-1, Ami-Ri, Bubal-eub
Ichon-si, Kyungki-Do
South Korea

Attention: Sang Ryu

Re: Application Received: 3/24/2004
Equipment Class: JBP-Part 15 Class B Computing Device Peripheral
Applicant Name: ImageQuest Co Ltd
FCC ID: PJIET1947L
TCB Name: Compliance Certification Services
731 Confirmation Number: TC652535

Gentlemen:

The application for the above equipment is hereby DISMISSED pursuant to Section 2.917(a) of the Rules for the following reasons.

Request by TCB in 26 May 2004 in correspondence 12096.

If you elect to refile for equipment authorization you must submit a currently dated and originally signed Form 731, accompanied by all data required by the Rule sections applicable to the equipment. The deficiencies listed above must be corrected before resubmitting. Do not resubmit the application with the same deficiencies or we may DENY the application pursuant to 2.919. You cannot reuse the FCC ID number on denied applications as you can with dismissed applications.

You are cautioned that marketing and importation of equipment in the United States bearing the referenced FCC Identifier is prohibited by Section 2.803 of the Rules. Violation of this regulation may subject you to the penalties provided in Sections 501 and 502 of the Communications Act of 1934, as amended.

Sincerely,

Martin Perrine
Electronics Engineer