

Chris Harvey

From: Phillip Raymond [Phillip.Raymond@enfora.com]
Sent: Sunday, March 14, 2004 7:56 PM
To: 'Chrisharveyemc@comcast.net'
Cc: 'MBosley@metlabs.com'
Subject: FW: Application review of the Portfolio MT#14796



3l0477rus1Rev3.pdf 3l0477rus2Rev2.pdf
f (545 KB) f (923 KB)

<<3l0477rus1Rev3.pdf>> <<3l0477rus2Rev2.pdf>>

-----Original Message-----

From: Tom Tidwell
To: Phillip Raymond; David Light
Sent: 3/12/04 5:09 PM
Subject: RE: Application review of the Portfolio MT#14796

Tom Tidwell
Frontline Manager
Nemko Dallas, Inc.
Phone: 972-436-9600
FAX: 972-436-2667
Email: tom.tidwell@nemkona.com

This message contains information that may be privileged or confidential and is the property of the Nemko Group. It is intended only for the person to whom it is addressed. If you are not the intended recipient, you are not authorized to read, print, retain, copy, disseminate, distribute, or use this message or any part thereof. If you receive this message in error, please notify the sender immediately and delete all copies of this message. Nemko Group cannot be held responsible for transmission errors nor confidentiality of mail and faxes.

Web: < <http://www.nemkona.com/> <<http://www.nemkona.com/>> >

-----Original Message-----

From: Phillip Raymond [mailto:Phillip.Raymond@enfora.com]
Sent: Friday, March 12, 2004 10:16 AM
To: David Light; Tom Tidwell
Subject: RE: Application review of the Portfolio MT#14796
Importance: High

Guys,

Any help here?

Thanks, Phil

-----Original Message-----

From: Phillip Raymond
Sent: Tuesday, March 09, 2004 2:17 PM

To: David Light (E-mail); Tom Tidwell (E-mail)
Cc: Scott Constien
Subject: FW: Application review of the Portfolio MT#14796
Importance: High

Tom or David,

The GSM3208, small portfolio, that Nemko did testing on has been held up in TCB and I have an urgent request to resolve some of the outstanding issues. Below are three items related to the testing that Nemko did that I need you to resolve for asap.

Here are the three items:

1. The Emission Designator provided in the test reports has 8 characters when it should only have 7 characters. Your Test Laboratory (Nemko) should be able to confirm that there is one extra character, likely to be the 2nd '0' which needs to be removed. Please contact them for confirmation. [Tom Tidwell] Please refer to revised test report attached.

7. Please obtain the ERP measurement value from the test laboratory who performed the RF testing. [Tom Tidwell] Please refer to revised test report attached.

8. Pt. 24 test report received. I will review, but please have the Laboratory provide the EIRP measurement value for the final Fundamental emissions.

[Tom Tidwell] Please refer to page 7 of Part 24 test report. I have attached a copy of the report in case you do not have it.

Please note the sense of urgency in resolving these items.

Thank you,

Phil

<<310477rus1Rev3.pdf>> <<310477rus2Rev2.pdf>>