

Report No.: 9808666

Tested By: Hong, Report No.: 9808666


Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |              |
|-------------|------|------|-------------------|----------|--------|-------|--------------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF 60dB  |

Final Measurement: X QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name  |
|----------------|-------|------|-------|
| 3              | 9k    | 30M  | EI078 |



PAGE 1

Ctrl. No.: N/A

Report No.: 9808666

Tested By: Hong, Report No.: 9808666

Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |       |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement Results:

| Frequency<br>MHz | QP Level<br>dBuV | QP Limit<br>dBuV |
|------------------|------------------|------------------|
| 0.46500          | 29.6             | 48.0             |
| 3.94000          | 26.5             | 48.0             |

\* limit exceeded

Ctrl. No.: N/A