

Report No.: 9808277

Tested By: Hong, Report No.: 9808277

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Report No.: 9808277

Tested By: Hong, Report No.: 9808277

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.48500	29.5	48.0
0.59500	27.7	48.0
0.85500	26.6	48.0
13.82000	9.2	48.0

* limit exceeded

Ctrl. No.: N/A