



Intertek Testing Services

ETL SEMKO

Report No.: 9910392


Tested By: Hong, Report No.: 9910392

Scan Settings (1 Range)

Frequencies			Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten
450k	30M	5k	10k	PK	20ms	AUTO LN OFF 60dB

Final Measurement: x QP
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078



PAGE 1

Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9910392

Tested By: Hong, Report No.: 9910392

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45500	37.5	48.0
0.62000	33.8	48.0
0.98000	32.8	48.0
1.04000	31.7	48.0
1.56500	26.7	48.0
1.69500	28.4	48.0

* limit exceeded

Ctrl. No.: N/A