

**dward**

---

**From:** oetech@fccsun27w.fcc.gov  
**Sent:** Friday, September 12, 2008 7:37 AM  
**To:** hotline@AmericanTCB.com  
**Subject:** Response to Inquiry to FCC (Tracking Number 907342) (TCB)

**Importance:** High



[FCC Home](#) | [Search](#) | [Updates](#) | [E-Filing](#) | [Initiatives](#) | [For Consumers](#) | [Find People](#)



**Office of Engineering and Technology**

□  
**Inquiry:**

---Reply from Customer on 09/08/2008---

Gentlemen On 9/3 the information you requested was uploaded. Do you have a decision on this PBA yet?  
Please advise if we can continue. thanks Dennis Ward

**Response:**

The grant condition and users manual must be consistent with the test setup. The transmitter must be installed in concrete, plastic and metal containers. The transmitter must be installed in a vertical downward direction as tested in the certification filing.

Do not reply to this message. Please select the [Reply to an Inquiry Response](#) link from the OET Inquiry System to add any additional information pertaining to this inquiry.