

Correspondence Summary Questions and Answers

May 9, 2003

SUBJECT: ASUS/TEK COMPUTER INC. - FCC ID: MSQWL300G

TCB Q-4: "Part 15.203: It is indicated that this device has provision for "One RF connector for optional external antenna" while the test report states that there is no external connector. The internal photo shows the external connector. Please, specify the connector type (e.g. reverse polarity xyz, drawings, and/or detailed description) and revise test report accordingly."

Applicant A-4: "This device isn't external antenna and antenna's connector apply to testing only. The user's manual has been statement as NOTE of page 44. Also, the application replace user manual as page 15."

TIMCO ENGINEERING INC.
849 NW State Road 45
Newberry, Florida 32669
<http://www.timcoengr.com>
888.472.2424 F 352.472.2030
bruno@timcoengr.com