

## Description of Permissive Change

This report is prepared for FCC class II permissive change. The difference compared with the original report is changed components for main board. Please refer to below for more details of the modification, which changes are not influence any RF functions.

- L4 changed to bead/0805
- Added C155.
- Added ferrite disk.
- Upgraded Flake graphite.