

## Comments and Response

- 2) Since calibration info is not fully shown (down to the day), please confirm that the BNC-BNC Coax is still in cal during date of test.

[Yes, the BNC-BNC coaxial cable used was still in calibration on the day of testing.](#)

- 7) For section 4.3.2 – please confirm that the digital device will be authorized under a sDoC.

The digital components in this device are employed only to enable operation of this product as a radio frequency device. The digital components do not control additional functions or capabilities. Per FCC Part 15.3(k) these components are not subject to further authorization under an sDoC.