




Photo 1: RF Board, Top View, PROX-100, Modified

Monopole version shown, Patch version uses exact same PCA. General assembly is same as original Report (LM05158A).




Photo 2: RF Board, Bottom View, PROX-100, Modified




Photo 3: RF Area, Top View, Shield Covers Removed, PROX-100, Modified




Photo 4: RF PA/BPF Area, Top View, Shield Covers Removed, PROX-100, Modified




Photo 5: RF BPF Area, Top View, Shield Cover in Place, PROX-100, Modified






Photo 3: PROX-100, Vertical, Ceiling Mount, Exploded View




Photo 4: PROX-100, Vertical, Ceiling Mount, , PCB, Top View




Photo 5: PROX-100, Vertical, Ceiling Mount, PCB, Bottom View




Photo 8: PROX-100, Horizontal, Wall Mount, Exploded View






Photo 9: PROX-100, Horizontal, Wall Mount, PCB, Component Side




Photo 10: PROX-100, Horizontal, Wall Mount, PCB, Circuit Side




Photo 11: RF Shield Removed




Photo 12: RF Shield Removed