



# Intertek Testing Services

## ETL SEMKO

Report No.: 0214702  
Talk Mode

Tested By: Hong, Report No.: 0214702

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |



Ctrl No.: N/A



# Intertek Testing Services

## ETL SEMKO

Report No.: 0214702  
Talk Mode

Tested By: Hong, Report No.: 0214702

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
| 450k  | 30M  | 5k   | 10k   | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement

no Results

Ctrl No.: N/A