



Intertek Testing Services

ETL SEMKO

Report No.: 0211692
Talk Mode

Tested By: Hong, Report No.: 0211692

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 0211692
Talk Mode

Tested By: Hong, Report No.: 0211692

Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB	

Final Measurement
Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
20.00000	29.4	48.0
28.00000	37.7	48.0

* limit exceeded

Ctrl No.: N/A