



Intertek Testing Services

ETL SEMKO

Report No.: 03026281
Talk Mode

Tested By: Hong, Report No.: 03026281

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 03026281
Talk Mode

Tested By: Hong, Report No.: 03026281

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO


Report No.: 03026282
Charging mode with
Charging Base

Tested By: Hong, Report No.: 03026282
Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV
Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services

ETL SEMKO

Report No.: 03026282
Charging mode with
Charging Base

Tested By: Hong, Report No.: 03026282

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement

no Results