

Appendix D. SAR Test Setup Photos

< EW-7811DAC >




Horizontal Up, Test Separation 5 mm



Horizontal Down, Test Separation 5 mm




Vertical Front, Test Separation 5 mm



Vertical Back, Test Separation 5 mm



Tip Mode, Test Separation 5 mm(Configuration 1)



Tip Mode, Test Separation 5 mm(Configuration 2)

< EW-7811UAC >




Horizontal Up, Test Separation 5 mm



Horizontal Down, Test Separation 5 mm



Vertical Front, Test Separation 5 mm



Vertical Back, Test Separation 5 mm



Tip Mode, Test Separation 5 mm(Configuration 1)



Tip Mode, Test Separation 5 mm(Configuration 2)

< EW-7811UAC1 >




Horizontal Up, Test Separation 5 mm



Horizontal Down, Test Separation 5 mm




Vertical Front, Test Separation 5 mm



Vertical Back, Test Separation 5 mm



Tip Mode, Test Separation 5 mm(Configuration 1)




Tip Mode, Test Separation 5 mm(Configuration 2)


< EW-7811UTCUACDAC >



Horizontal Up, Test Separation 5 mm



Horizontal Down, Test Separation 5 mm



Vertical Front, Test Separation 5 mm



Vertical Back, Test Separation 5 mm



Tip Mode, Test Separation 5 mm