

APPENDIX 3: Photographs of test setup

Radiated Emission




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Worst Case Position

ECU
Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)


X-axis



Y-axis



Z-axis



Outside Antenna
Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999


Facsimile : +81 596 24 8124

Worst Case Position


Inside Antenna
Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)
X-axis



Y-axis



Z-axis



Rear Antenna
Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)
X-axis



Y-axis



Z-axis



Worst Case Position

Immobilizer Antenna
Below 30 MHz: X-axis
Above 30 MHz (Horizontal: X / Vertical: X)
X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124