

Sporton International Inc.

No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan Hsiang, Tao Yuan Hsien, Taiwan,
R.O.C.

Tel: 886-3-327-3456 ; Fax: 886-3-328-4978

Date: June 7, 2011

Statement

We, Sporton International Inc., states that the power in watts in DSS report of our device, FCC ID: NM8PG58110, has been mis-calculated from dBm. The correct power in watts has been updated in the test report. Except for the modification mentioned above, no other portion of this report is changed. Please kindly replace the original DSS report with the new-submitted one.

Should you have any question, please contact me directly. Thanks!

Sincerely yours,



Jones Tsai