

Report No.: 9800841

Tested By: Hong, Report No.: 9800841

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



PAGE 1

Ctrl. No.: N/A

Report No.: 9800841

Tested By: Hong, Report No.: 9800841

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A