

To: "tjohnson@AmericanTCB.com" <tjohnson@AmericanTCB.com>
Subject: FCC ID: NTAXMETER7

FCC ID: NTAXMETER7

In reply to e-mail dated June 16, 2003

Dear Mr. Johnson,

Below are the answers to your questions.

1. Please find an updated "Internal photographs" file, in which antenna placement is shown, submitted via " Upload for application NTAXMETER7 ATCB000503"", Internal photographs folder on June 19, 2003.
2. Please find an updated Exposure exhibit, submitted via "Upload for application NTAXMETER7 ATCB000503", RF exposure info folder on June 19, 2003.
3. Please find an updated Test report, submitted via "Upload for application NTAXMETER7 ATCB000503", Test report folder on June 19, 2003.
4. Tadiran telematics confirms that the worst case duty cycle is approximately 5.5 ms of transmission every 10 seconds.

With great respect,

Valeria