

Timco Engineering Inc.
849 NW State Road 45
Newberry FL 32669

To: Tim Harrington
tharring@fcc.gov
FCC Equipment Authorization Branch

Re: FCC ID: NTXINT900

Applicant: Midway Services Inc
Correspondence Reference Number: 9209
731 Confirmation Number: TC448821
Date of Original Email: 08/21/2003

Subject: audit

Dear Tim:

Thank you for your comments on this product. Yes, indeed several errors was made. Some of the external photos, user's manual, block diagram, and theory of operation are from the NTX900. We are uploading the above revised items. Below I have enclosed your comments followed by my replies.

1) Several plots in EMC report are identical to FCC ID NTX900. Please describe how both IDs are electrically identical, or retest if appropriate.

The NTXINT900 transmitter section is electrically identical to NTX900 and therefore most of the data is identical. Please note the radiated data is different and is reported correctly.

2) User manual is same as FCC ID NTX900. External photos show empty box. Please clarify device and antenna installation conditions, e.g., using updated complete manual, external photos, etc.

We are uploading the correct user's manual and new external photos.

3) MPE exhibit refers to plastic cover over EUT - seems to be NTX900, please revise.

The MPE exhibit as submitted is incorrect and we are uploading a corrected MPE exhibit.

Regards,

Mario de Aranzeta