







Radar Vision 1000- Assembly with Cover Removed




Radar Vision 1000- Bottom Side of Cover





1.28 GHz Oscillator Top




1.28 GHz Oscillator Bottom












Baseband-Top




Baseband-Bottom





LNA Board-Top with Panel On




LNA Board-Top Without Panel









Timer Board-Top Without Panel



Timer Board-Bottom




ASIC 1 Module Top




ASIC 1 Module Bottom


5007-0009 VER 2.0 ECO:
 INTERFACE SN:
 ©TDSI

Interface Board - Back







Processor - Front



Processor - Back




Conditioner-Top





Conditioner-Back

Power Supply Board - Front




Power Supply Board - Back





LCD Display - Front



LCD Display - Back