



FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8a Photo # 1
Internal View - Chassis Inside



FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8b Photo # 2
Internal View – Chassis Ouside



FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8c Photo # 3
Internal View – Button Assy




FCC ID: NVJ AR8200B


Report # 86060-1

Page # 8d Photo # 4


Internal View - RF Section Top





FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8e Photo # 5
Internal View - RF Section Rear




FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8f Photo # 6
Internal View-Battery & Interface Top







FCC ID: NVJ AR8200B
Report # 86060-1
Page # 81 Photo # 9
Internal View – Antenna Section Rear




FCC ID: NVJ AR8200B

Report # 86060-1

Page # 8j Photo # 10

Internal View-Keypad & Display Top




FCC ID: NVJ AR8200B


Report # 86060-1

Page # 8k Photo # 11


Internal View-Keypad & Display Rear



FCC ID: NVJ AR8200B
Report # 86060-1
Page # 81 Photo # 12
Internal View - RF Section Top



FCC ID: NVJ AR8200B
Report # 86060-1
Page # 8m Photo # 13
Internal View – Sub-board under shield



FCC ID: NVJ AR8200B

Report # 86060-1

Page # 8n Photo # 14

Internal View - Sub-board under shield

