



7/F, Block F4, TCL Communication Technology Building, TCL International E City, Zhong Shan Yuan
Road, Nanshan District, Shenzhen, Guangdong, P.R. China 518052
TEL: 0086-755-36611722
FAX: 0086-75536612000-81722

Declaration of changes from Initial to Variant

General: 8391X is a variant product of 8091

- **SOFTWARE MODIFICATIONS:**

- Protocol Stack changes: **NO**
- MMS/STK/USAT/USIM changes: **NO**
- DM/SUPL/VT/FUMO/SWP/HCI: **NO** (indicated the changed items if yes)
- Other changes detailed: **yes** , mode name change 8091 to 8391X , SW version change to DGB , Product Name change to tablet PC , FCC ID change to NXM-8391X , RF parameters did not change.

- **HARDWARE MODIFICATIONS:**

- Band changes: **NO**
- PCB Layout changes: **NO**
- Main RF components changes: **NO**

GSM	Antenna	AP	Modem	Transceiver	Power Amplifier	Rx SAW Filter	ASM
GSM850	NO	NO	NO	NO	NO	NO	NO
GSM900	NO	NO	NO	NO	NO	NO	NO
GSM1800	NO	NO	NO	NO	NO	NO	NO
GSM1900	NO	NO	NO	NO	NO	NO	NO

[illegible][illegible]

Band 41	NO	NO	NO	NO	NO	NO	NO	NO	NO
---------	----	----	----	----	----	----	----	----	----

	Antenna	AP	Modem	Transceiver	Power Amplifier	Balun	Band pass filter	Diplexer
Bluetooth	NO	NO	NO	NO	NO	NO	NO	NO
Wi-Fi	NO	NO	NO	NO	NO	NO	NO	NO
GPS	NO	NO	NO	NO	NO	NO	NO	NO

- FM changes: **No**
- LCD/ Speaker/ Camera/ Vibrator changes: (indicated the changed items if yes) **No**
- Other changes detailed:

● **MECHANICAL MODIFICATIONS:**

- Use new metal front/back cover or keypad: **NO**
- Mechanical shell changes: **NO**
Whole size of EUT: **NO**
Distance of Ear reference point to bottom of handset: **NO**
Other trinkets to change the surface of handset: **NO**
- Other changes detailed: **yes** , rear housing brand name and manufacturer change
The charger and USB cable PN number has changed, The hardware hasn't changed.no affect the EMC result.

8317X charger	8091 charger
CBA0058AGNC5	CBA0058AAAC5/ CBA0058AAAC7

USB change CDA0000123C8 to CDA0000182C2

APPROVED BY:

Project Manager:

Signature:

Date: 2021-07-25

Gong Shizhou