

A

June 14, 2000

re: ea97821

To Whom It May Concern:

SUBJECT:

Please find the following additional exhibits submitted for the Harmonix Gigalink:

- revised FCC ID label – Harmonix requests a change from the original submittal to the ID shown on the label submitted on 13 June
- discussion of FCC Identifier needed for transmission
- letter from FCC re: FCC identifier
- report addressing FCC part 15.255 and associated sections

Sincerely,

Robert F. Martin
Sr. Technical Manager
Intertek Testing Services

70 CODMAN HILL RD
BOXBOROUGH MA 01462
USA