




Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:44:03


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:13:53


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:43:01


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:10:00


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 13:35:25


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:54:39


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:15:09


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 11:25:11


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 10:50:41


TEST MODE 2

(Without GPS-1 Synchronizer)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:41:03


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 15:10:55


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:39:47


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 14:11:41


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 13:37:00


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:56:25


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 12:16:42


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 11:27:26


TEST MODE 3

(Without 1 PPS Timing Signal)



Company: Highway Information Systems, Inc.
Model Tested: DRTXM3
Report Number: 9982

1250 Peterson Drive, Wheeling, Illinois 60090



Date: 6.JAN.2003 10:45:57

TEST MODE 3

(Without 1 PPS Timing Signal)